

Section V · STORAGE HAZARDS		
Stability unstable <input type="checkbox"/>	Conditions to avoid	
stable <input checked="" type="checkbox"/>		
Incompatibility (materials to avoid)	:	Avoid high temperature
List hazardous products of decomposition	:	CO, CO2, NOx
Hazardous polymerization	May occur <input type="checkbox"/> will not occur <input checked="" type="checkbox"/>	Condition to avoid Heat, high temperature and fire sources
Section VI · HEALTH HAZARDS		
1. Acute		2. Chronic *
Signs and symptoms of overexposure	:	
Medical conditions generally aggravated by exposure	:	Ingestion may result in liver and kidney damage
Chemical listed as carcinogen	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Emergency and first aid procedures	:	
Routes of entry	Emergency procedure	Seek medical advice
Inhalation	Remove from exposure rest & keep warm	<input type="checkbox"/>
Eyes	Wash with water	<input checked="" type="checkbox"/>
Skin	Wash with soap and water	<input type="checkbox"/>
Ingestion	Wash out mouth and give water to drink	<input checked="" type="checkbox"/>
Section VII · SPECIAL PRECAUTIONS		
Special precautions to be taken in handling storage	:	Avoid skin and eye contact. Close cap after used.
Other precautions	:	NONE
Steps to be taken in case material is released or spilled	:	Wash off ink and wash with detergents and water
Waste disposal method	:	Dispose the waste ordinarily.
Section VIII · SPECIAL PROTECTION INFORMATION / CONTROL MEASURES		
Respiratory protection (specify type)	:	Not necessary
Ventilation	Local exhaust <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/>	Mechanical (general) n.a <input type="checkbox"/> Other n.a. <input type="checkbox"/>
Skin and eye protection	:	not required but use of safety goggles are preferable
Work / hygienic practices	:	not required,use protective clothing if necessary
Not applicable = n.a Not determined = n.d		